



THE LEADER IN HI-TECH TRAINING

800-643-7822 www.eptac.com



ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director

Welcome to the EPTAC Webinar Series:

Mid Year Update

A Review of Some Commonly Asked Questions

You are connected to our live presentation delivered via the internet. The webinar will begin shortly.





THE LEADER IN HI-TECH TRAINING

800-643-7822 www.eptac.com



ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director

Attendee Quick Reference

 You can ask questions by typing text directly to the presenter using the "Question and Answer" box

Control Panel Features:


Once you have joined our Webinar, you will see this GoToWebinar Control Panel and Grab Tab. The control panel contains three panes that can be expanded or collapsed by clicking the arrow on the left side of each pane.

To Leave a Webinar:

1. From the Attendee Control Panel *File* Menu, select *Exit – Leave Webinar*.

2. On the Leave Webinar?

Confirmation dialog box, click Yes.





THE LEADER IN HI-TECH TRAINING

800-643-7822 www.eptac.com



ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director



Mid Year Update

A Review of Some Commonly Asked Questions





Topics



THE LEADER IN HI-TECH TRAINING

800-643-7822 www.eptac.com



ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director

- Poor wetting and its causes
- The impact of cutting into the solder joints while trimming leads
- Meniscus as related to the soldering requirements
- Acceptability requirements for wire wrapping to a pierced terminal





THE LEADER IN HI-TECH TRAINING

800-643-7822 www.eptac.com



ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director

Poor Wetting And Its Causes

- Definition:
 - Wetting = The ability of a metal to be wetted by another metal creating an intermetallic bond.
 - Wetting is the metallurgical bond of two separate metals with a third metal, i.e. solder.
 - In our case a copper-tin intermetallic compound



0 S N С


THE LEADER IN HI-TECH TRAINING

800-643-7822 www.eptac.com

Bonding Process



ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director





ELECTRONICS TRAINING


THE LEADER IN HI-TECH TRAINING

800-643-7822 www.eptac.com

Wetting Angles



ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director



7



ELECTRONICS TRAINING


THE LEADER IN HI-TECH TRAINING 800-643-7822

www.eptac.com

Equilibrium of Wetting



ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director



8



ELECTRONICS TRAINING

THE LEADER IN HI-TECH TRAINING

800-643-7822 www.eptac.com

Poor Wetting And Its Causes



ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director

- Two reasons product does not solder
 - Oxidized intermetallic coating
 - Exposed intermetallic surfaces
 - Contamination of the surfaces to be soldered






THE LEADER IN HI-TECH TRAINING


800-643-7822 www.eptac.com



ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director

Specification Wetting Requirements for Class 3 Products









THE LEADER IN HI-TECH TRAINING

800-643-7822 www.eptac.com




ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director

Types of Solderability Defects



a) Dewetting

b) Nonwetting



IPC-002b-b-2a, b-2b, b-2c

Figure B-2 Types of Solderability Defects



ELECTRONICS TRAININ

THE LEADER IN HI-TECH TRAINING


800-643-7822 www.eptac.com


Poor Wetting And Its Causes



ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director

 Wetting implies the surfaces are clean and oxide free









THE LEADER IN HI-TECH TRAINING


800-643-7822 www.eptac.com

Poor Wetting And Its Causes



ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director

Non Wetting



Defect - Class 1,2,3

- Solder has not wetted to the land or termination where solder is required.
- Solder coverage does not meet requirements for the termination type.

Figure 5-36





THE LEADER IN HI-TECH TRAINING


800-643-7822 www.eptac.com

Poor Wetting And Its Causes



ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director

Dewetting



Defect - Class 1,2,3

 Evidence of dewetting that causes the solder connection to not meet the SMT or through-hole solder fillet requirements.






THE LEADER IN HI-TECH TRAINING

Poor wetting and its causes

800-643-7822 www.eptac.com



ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director







ELECTRONICS TRAINING

THE LEADER IN HI-TECH TRAINING

800-643-7822 www.eptac.com

Check the Specs



ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director

- J-STD-002 Solderability Tests for Component Leads, Terminations, Lugs, Terminals and Wires
- J-STD-003 Solderability Test for Printed Boards





THE LEADER IN HI-TECH TRAINING

800-643-7822 www.eptac.com

Cutting Into the Solder Joint



ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director

- This is a new requirement for Class 3 products, where the solder joint must be reflowed when cutting the lead through the solder joint.
 - J-STD-001 Para 6.1.4 Lead Trimming
 - IPC-A-610 Section 7.3.5.9 Lead Cutting After Soldering





THE LEADER IN HI-TECH TRAINING 800-643-7822


www.eptac.com

Cutting into Solder Joints



ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director





Defect - Class 1,2,3

· Evidence of fracture between lead and solder fillet.

Defect - Class 3

 Lead trimming that cuts into the solder fillet and is not reflowed.



THE LEADER IN HI-TECH TRAINING


800-643-7822 www.eptac.com




ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director



Meniscus in Solder IPC-A-610 Rev E







Acceptable - Class 1

- Components with a coating meniscus can be mounted with the meniscus into the solder provided:
- 360° wetting on the secondary side.
- Lead coating meniscus is not discernible within the connection on the secondary side.

Acceptable - Class 2,3

• Coating meniscus is not in the plated-through hole and there is discernible clearance between the meniscus and the solder fillet.

Process Indicator - Class 2

• Coating meniscus is in the plated-through hole but solder joint meets the requirements of Table 7-4.

Defect - Class 3

- Coating meniscus is in the plated-through hole.
- · Coating meniscus is embedded in the solder connection.



THE LEADER IN HI-TECH TRAINING

800-643-7822 www.eptac.com



ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director



Meniscus in Solder J-STD-001 Rev D & E

001 Rev D and Rev E States:

6.1.6 Coating Meniscus In Solder For Class 1 and 2 as an exception to Tables 6-4 or 6-5, as appropriate for supported or unsupported holes, on the solder destination side

the meniscus may be covered by solder but on the solder source side there shall⁴ be 360° visible solder wetting and no visible coating meniscus in the solder connection. Solder connections shall⁵ meet the requirements of Tables 6-4 or 6-5, as appropriate.

(4) Class	1-Defect
Class	2-Defect
Class	3-Defect
(5) Class	1-Not Est
	2-Not Est
Class	3-Defect





THE LEADER IN HI-TECH TRAINING

800-643-7822 www.eptac.com



ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director

Acceptability for Wire Wrap



Figure 6-51



TARGET:

The main requirement is that the wire passes through the eye of the terminal and contacts at least two nonadjacent sides of the terminal

Acceptable 2, 3

 Wire wrap equal to or greater than 90° or wire contacts both sides of the terminal.

Figure 6-52



ELECTRONICS TRAINING

THE LEADER IN HI-TECH TRAINING

800-643-7822 www.eptac.com



ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director

Acceptability for Wire Wrap




Figure 5-13 Pierced or Perforated Terminal Wire Wrap Table 5-9 Pierced/Perforated Wire Placement

Criteria	Class 1	Class 2	Class 3
<90° wrap	Accept	Defect	
≥90° wrap	Accept		
>360° and wire end overlaps itself1	Accept	Defect	
Wire does not pass through the eye and contact two sides of the terminal	Accept	Defect	
Wire end violated minimum electrical clearance	Defect		

22





THE LEADER IN HI-TECH TRAINING

800-643-7822 www.eptac.com





ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director




Figure 6-53

Acceptable Class 1, Defect Class 2, 3

Wire wrap is less than 90° or wire does not contact both sides of the terminal





THE LEADER IN HI-TECH TRAINING

800-643-7822 www.eptac.com



ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director

Customer request, Good or Bad?





- In this case the wire completely wraps over the terminal.
- Hole in terminal is too small for wire to be installed through the hole so the terminal was treated as a turret terminal.
- Wire is wrapped 180 around the terminal post like a turret terminal.



ELECTRONICS TRAINI

THE LEADER IN HI-TECH TRAINING

800-643-7822 www.eptac.com





ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director Just keeping you informed regarding information which I think may be useful to all of you

Thank You



ELECTRONICS TRAINING

THE LEADER IN HI-TECH TRAINING

800-643-7822 www.eptac.com

Further Information



ABOUT THE PRESENTER Leo Lambert Vice President, Technical Director

For questions regarding this webinar, please contact Leo Lambert at <u>leo@eptac.com</u>

For information on any of EPTAC's or IPC's Certification Courses, please visit our website at <u>http://www.eptac.com</u>